







-  Major Barrier
-  Disconnected Reach
-  Lost Salmon Habitat Due to Disconnection or Dewatering
-  Current Connected Reach
-  Lowland
-  Upland

White area represents former historical lowland floodplain and estuarine intertidal habitat as well as drained historical lakes



The Transformed Watershed